

FASTCAM-Series DRIVER CD-ROM Rev. 2.40.37			Release Note
			2006/05/23
CD-ROM Revision FASTCAM-Series DRIVER CD-ROM Rev.2.40.37 (Domestic/Overseas common shipment version)			
PFV Revision PFV Ver.2437 SDK Ver.2977			
The contents of a folder in CD-ROM			
PFV setup	PFVSETUP		
Driver	Device driver FASTCAM-Ultima1024 FASTCAM-Ultima SE FASTCAM-PCI FASTCAM-PCI R2 FASTCAM-X1280PCI FATSCAM-ultima APX FATSCAM-ultima 512 FATSCAM-512PCI FASTCAM-APX RS FASTCAM-1024PCI		
SDK	FASTCAM series correspondence SDK ,Sample code ,SDK document		
Doc	PDF file inclusion of each camera manual ,Release Note		
DirectX	Microsoft DirectX Run time		

Functional addition		Bug fixed	Others
No.	Contents		Hardware Update
FASTCAM-APX RS			
1	Dual Slope shutter function has been added to color models of the FASTCAM-APX RS (firmware version 1.16 and later needed).		Needed
2	Bug has been corrected in the FASTCAM-APX RS which caused misalignment of data timing between IRIG and MCDL in the output file when the RANDOM CENTER or RANDOM MANUAL trigger mode is used.		
3	FcamGEth.dll changed (Ver.1.006).		
4	Fcam1394.dll changed (Ver2.011).		
5	FcamOpt.dll changed (Ver.1.022).		
FASTCAM-ultima APX			
6	Bug has been corrected in the FASTCAM-ultima APX which caused misalignment of data timing between IRIG and MCDL in the output file when the RANDOM CENTER or RANDOM MANUAL trigger mode is used.		
FASTCAM-ultima512			
7	Bug has been corrected in the FASTCAM-ultima 512 which caused misalignment of data timing between IRIG and MCDL in the output file when the RANDOM CENTER or RANDOM MANUAL trigger mode is used.		
Miscellaneous			
8	FASTCAM-APX RS Hardware Manual updated (Japanese/English)		
9	FASTCAM-ultima APX Hardware Manual updated (Japanese/English)		
10	FASTCAM-ultima 512 Hardware Manual updated (Japanese/English)		
11	PFV Application Manual updated (Japanese/English)		

End of documents